


## SERVICE SUGGESTION

For

Floating row cleaners on Case IH 5310, 930, 940, 950  
Pull-Type and mounted tool bars.



After initial use, periodically spray WD-40 in designated areas. This will allow the parallels and discs to continue to float freely, thereby providing optimum performance and service life of the unit.